

Digital Force Gauge SAUTER FL-M



Powerful digital force gauge with graphic assisted display for tensile and compressive force measurements with external load cell

| Features | Technical data | Accessories |
|---|---|---|
| <ul style="list-style-type: none"> Premium force gauge with external measuring cell, tension loops included with delivery Turnable display with backlight Peak-Hold function to capture the peak value or Track function for continuous display of measurement Metal housing for durable use in harsh environmental conditions Can be mounted on all SAUTER test stands starting 1 kN Capacity display: A bar lights up to show how much of the measuring range is still available Measuring with tolerance range (limit-setting function): Upper and lower limit adjustable, in pull and push direction. The process is supported by a visual signal Internal memory for up to 500 measurement values Continuous analogue output: Linear voltage signal in dependence to the load (-2 to +2V) USB data interface, as standard Selectable measuring units: N, kN, kgf, ozf, lbf Delivered in a robust carrying case | <ul style="list-style-type: none"> Transfer rate to PC: approx. 25 measured values per second Measuring precision: 0,2 % of [Max] Overload protection: 120 % of [Max] Overall dimensions WxDxH 175x75x30 mm Dimensions load cell WxDxH 76,2x51x19 mm (FL 2K), 76,2x51x28 mm (FL 5K, 10K, 20K) Thread: M12 Rechargeable battery pack integrated, as standard, operating time up to 10 h without backlight, charging time approx. 8 h Net weight approx. 1,4 kg | <ul style="list-style-type: none"> Plug-In for data transfer of measuring data from the measuring instrument and transfer to a PC, e.g. in Microsoft Excel®, SAUTER AFI-2.0, see internet Data transfer software with graphic display of the measurement process, force-time, SAUTER AFH FAST USB cable, included with the delivery, can be ordered separately, USB/PC connection cable (USB-A/USB mini), SAUTER FL-A01 RS-232 adapter cable, SAUTER FL-A04 Holders for object fixation and other accessories, please see internet |

| | |
|---|--|
| STANDARD | OPTION |
| PEAK PUSH/PULL MEMORY RS 232 USB ANALOG TOL ZERO ACCU 230 V 1 DAY UNIT | SOFTWARE DAkkS ISO |

| Model | Measuring range | Readability | Option DAkkS Calibration Certificate (≤ 5 kN)/Factory calibration certificate (> 5 kN) | | |
|--------|-----------------|-------------|--|-------------------|---------------------------|
| | | | Tensile force | Compressive force | Tensile/Compressive force |
| SAUTER | [Max] N | [d] N | KERN | KERN | KERN |
| FL 2K | 2500 | 1 | 963-162 | 963-262 | 963-362 |
| FL 5K | 5000 | 2 | 963-163 | 963-263 | 963-363 |
| FL 10K | 10000 | 5 | 961-164 | 961-264 | 961-364 |
| FL 20K | 20000 | 10 | 961-164 | 961-264 | 961-364 |

Further calibration options on request

| | | | |
|---|---|--|---|
|  <p>Adjusting program (CAL) For quick setting of the instrument's accuracy. External adjusting weight required</p> |  <p>Bluetooth* data interface To transfer data from the balance/measuring instrument to a printer, PC or other peripherals</p> |  <p>Measuring units Weighing units can be switched to e.g. non-metric. Please refer to website for more details</p> |  <p>Conformity assessment Models with type approval for construction of verifiable systems</p> |
|  <p>Calibration block Standard for adjusting or correcting the measuring device</p> |  <p>WIFI data interface To transfer data from the balance/measuring instrument to a printer, PC or other peripherals</p> |  <p>Measuring with tolerance range (limit-setting function) Upper and lower limiting can be programmed individually. The process is supported by an audible or visual signal, see the relevant model</p> |  <p>DAkkS calibration possible The time required for DAkkS calibration is shown in days in the pictogram</p> |
|  <p>Peak hold function Capturing a peak value within a measuring process</p> |  <p>Data interface infrared To transfer data from the measuring instrument to a printer, PC or other peripheral devices</p> |  <p>Protection against dust and water splashes IPxx The type of protection is shown in the pictogram cf. DIN EN 60529:2000-09, IEC 60529:1989 +A1:1999+A2:2013</p> |  <p>Factory calibration (ISO) The time required for factory calibration is specified in the pictogram</p> |
|  <p>Scan mode Continuous capture and display of measurements</p> |  <p>Control outputs (optocoupler, digital I/O) To connect relays, signal lamps, valves, etc.</p> |  <p>ZERO Resets the display to "0"</p> |  <p>Package shipment The time required for internal shipping preparations is shown in days in the pictogram</p> |
|  <p>Push and Pull The measuring device can capture tension and compression forces</p> |  <p>Analogue interface To connect a suitable peripheral device for analogue processing of the measurements</p> |  <p>Battery operation Ready for battery operation. The battery type is specified for each device</p> |  <p>Pallet shipment The time required for internal shipping preparations is shown in days in the pictogram</p> |
|  <p>Length measurement Captures the geometric dimensions of a test object or the movement during a test process</p> |  <p>Analogue output For output of an electrical signal depending on the load (e.g. voltage 0 V - 10 V or current 4 mA - 20 mA)</p> |  <p>Rechargeable battery pack Rechargeable set</p> | |
|  <p>Focus function Increases the measuring accuracy of a device within a defined measuring range</p> |  <p>Statistics Using the saved values, the device calculates statistical data, such as average value, standard deviation etc.</p> |  <p>Plug-in power supply 230V/50Hz in standard version for EU. On request GB, AUS or US version available</p> | |
|  <p>Internal memory To save measurements in the device memory</p> |  <p>PC Software To transfer the measurement data from the device to a PC</p> |  <p>Integrated power supply unit Integrated, 230V/50Hz in EU. More standards e.g. GB, AUS or US on request</p> | |
|  <p>Data interface RS-232 Bidirectional, for connection of printer and PC</p> |  <p>Printer A printer can be connected to the device to print out the measurement data</p> |  <p>Motorised drive The mechanical movement is carried out by an electric motor</p> | |
|  <p>Profibus For transmitting data, e.g. between scales, measuring cells, controllers and peripheral devices over long distances. Suitable for safe, fast, fault-tolerant data transmission. Less susceptible to magnetic interference</p> |  <p>Network interface For connecting the scale/measuring instrument to an Ethernet network</p> |  <p>Motorised drive The mechanical movement is carried out by a synchronous motor (stepper)</p> | |
|  <p>Profinet Enables efficient data exchange between decentralised peripheral devices (balances, measuring cells, measuring instruments etc.) and a control unit (controller). Especially advantageous when exchanging complex measured values, device, diagnostic and process information. Savings potential through shorter commissioning times and device integration possible</p> |  <p>KERN Communication Protocol (KCP) It is a standardized interface command set for KERN balances and other instruments, which allows retrieving and controlling all relevant parameters and functions of the device. KERN devices featuring KCP are thus easily integrated with computers, industrial controllers and other digital systems</p> |  <p>Fast-Move The total length of travel can be covered by a single lever movement</p> | |
|  <p>Data interface USB To connect the measuring instrument to a printer, PC or other peripheral devices</p> |  <p>GLP/ISO record keeping of measurement data with date, time and serial number. Only with SAUTER printers</p> | | |